

**CITY OF BALTIMORE WET WEATHER CONSENT DECREE
SMOKE AND DYED WATER TESTING FORM**

Sewershed: Low Level
Subsewershed: 44

Company: REI/DRAYCO

Date: 09/03/2008

Test Type: Smoke

Ground Condition:
Dry: X Damp: _ Wet: _


Supervisor: E.R. Crew: 04

Manhole ID: S17M__039MH

Test ID: 1029-597

Notifications Made: __X__
Residents, Fire, 311

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 597	Date: 09/03/2008	Basin: LL - 44	Manhole ID: S17M__039MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: S19K__039MH			

Source Type: 10 MH Frame	Sector: 01 Public	
Location: 02 Asphalt	Severity: 01 No Smoke	Drainage Area: 0

Comments: WATER IS FLOWING INTO SANITARY SEWER FROM AROUND MANHOLE FRAME OF MANHOLE S19K__039MH.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-597_OB01-01.jpg